Service		Revised Fee
Commercial Inspections		
Less than 500 sq ft		$ 72.50
500 - 2,499 sq ft		$ 145.00
2,500 – 5,000 sq ft		$ 200.00
5,001 – 10,000 sq ft		$ 255.00
Each additional 50,000 sq ft		$ 255.00
Fire Pump Inspection		$ 55.00
Standpipe Inspection		$ 90.00
Fire Sprinkler Inspection		$ 145.00
Fire Alarm Inspection		$ 145.00
Fire Alarm/Fire Sprinkler Inspection Combo		$ 225.00

Multiple Family Residential Fire Inspections – <u>To be phased in over the next 6 years. See below.</u>

<u>Number of Units</u>	<u>50% increase in FY18</u>	<u>75% increase in FY20</u>	<u>100% increase in FY22</u>
3 -15 Units	$ 72.50	$ 108.75	$ 145.00
16 – 25 Units	$ 100.00	$ 150.00	$ 200.00
26 – 35 Units	$ 127.50	$ 191.25	$ 255.00
36 – 45 Units	$ 157.50	$ 236.25	$ 315.00
Over 45 Units	$ 185.00	$ 277.50	$ 370.00

Service		Revised Fee
Commercial / Multi-Family Photo Voltaic Inspection		$ 145.00
Non-Portable Storage Container Inspection		
First Unit		$ 90.00
Each Additional Unit		$ 55.00
ALF Evacuation Drill Inspection		$ 145.00
Miscellaneous Inspections		$ 145.00
Fire Hydrant Flush		

Service		Revised Fee
First Unit/Hydrant		$ 90.00
Each Additional Unit/Hydrant		$ 55.00
Witness Hydrant Fire Flow Test		$ 200.00
Special Agent System Inspection (bi-annual)		$ 145.00
Commercial Cooking Fire Suppression Inspections (bi-annual)		$ 145.00
Food Truck Inspections Commercial Cooking Fire Suppression Inspections (annual)		$ 90.00
Safety Re-Inspection Fee		See Below

Safety Re-Inspections

The initial inspection fees include the cost of the initial inspection and one follow up inspection if there was a failed initial inspection. Because of the public safety nature of the Safety Inspections there is a strong need to ensure that violations are fixed quickly. As such a second failed inspection for the same violation will require a third inspection and the fee for the third inspection will be the cost of the initial inspection. The fee will double for each additional failed inspection for the same violation.